

January 24, 2013

Service bulletin SB E-01.7

The acceptable sweep rate for the model E-01 ELT is 2 to 4 Hz. If the sweep rate falls below the 2 Hz rate replace resistor R6 with a 80 ohm resistor and re-test.

